Example workshop

Technician: Example inspector

REPORT

VEHICLE DISCLOSURE REPORT

10/26/2026

EXAMPLE

Toyota Corolla Hybrid · 2021


Date	Mileage	Customer
10/26/2026	**45,000 mi**	**Example customer**

INITIAL CONDITION / DEFECTS


Illustrative visual pre-sale inspection; superficial marks on the front left wing.

BODY DEFECT MAP


Top view · front at top



Left side · front to the left



Right side · front to the right



Recorded defects: 1 · Unmarked areas do not confirm inspection
Front left fender · Scratch - Illustrative superficial marks. - No linked photos.
Highlighted panels indicate recorded defects, not an automatic assessment.
No fault-free claim; review actual scanned modules.
Paint thickness readings alone do not certify factory paint.

USED-CAR INSPECTION

Fictional example; unrecorded checks are not considered completed.

CUSTOMER ACKNOWLEDGEMENT

The customer received the findings and, where relevant, risks of critical defects. Signature acknowledges receipt, not repair authorization or waiver of rights.

CUSTOMER - ACKNOWLEDGED

Example customer

10/26/2026, 9:10:00 AM

Signed by: Example customer · Signed at: 10/26/2026, 9:10:00 AM

PHOTOS



Photo 1 - Vehicle identification - Generated illustrative image; not an inspected vehicle.

Not enough photos for a full inspection (2-4 real photos recommended).