Example workshop

Technician: Example inspector

REPORT

FLEET VEHICLE HANDOVER

10/26/2026

EXAMPLE

Dacia Duster · 2021


Date	Mileage	Customer
10/26/2026	**45,000 mi**	**Example customer**

HANDOVER


Operation: Checkout
Driver / custodian: Example driver
Fuel / charge: 3/4
Keys: 2
Accessories: Locking-wheel-bolt adapter, warning triangle and first-aid kit.
Condition recorded before handover. The marked scratch on the rear right door must be compared with the original sheet and photographs at return.

BODY DEFECT MAP


Top view · front at top



Left side · front to the left



Right side · front to the right



Recorded defects: 1 · Unmarked areas do not confirm inspection
Rear right door · Scratch - Demonstration marker: light surface mark on the door. Model photographs are not evidence of this defect. - No linked photos.
Highlighted panels indicate recorded defects, not an automatic assessment.

Inspector conclusion

Demonstration handover sheet. A return inspection has not yet been recorded, and liability for damage is not assigned.

CUSTOMER ACKNOWLEDGEMENT

The customer received the findings and, where relevant, risks of critical defects. Signature acknowledges receipt, not repair authorization or waiver of rights.

CUSTOMER - ACKNOWLEDGED

Example driver

10/26/2026, 9:10:00 AM

Signed by: Example driver · Signed at: 10/26/2026, 9:10:00 AM

PHOTOS



Photo 1 - Vehicle identification - Generated illustrative image; not an inspected vehicle.

Not enough photos for a full inspection (2-4 real photos recommended).