Example workshop

Technician: Example inspector

REPORT

LPG system - inspection

10/26/2026

EXAMPLE

Dacia Logan 1.0 GPL · 2020

Date	Mileage	Customer
10/26/2026	**45,000 mi**	**Example customer**

Recorded checks are OK

No issues were recorded.

6	0	0
OK	Needs attention	Critical

System

System / ECU brand	Example system
Tank type	Toroidal
Tank expiry date	2030-05-01
Odometer	39767.756 mi

Checks

CHECK	VALUE / NOTE	STATUS
Leak test		● OK
Leak test method	Electronic detector	
Multivalve		● OK
Reducer / vaporiser		● OK
LPG injectors		● OK
Pipes and hoses		● OK
Liquid-phase filter	Replaced	
Vapour-phase filter	Replaced	
Petrol-LPG switchover		● OK

Conclusions

Notes and recommendations	Filters replaced, no leaks.

Workshop technical check. It does not replace the official LPG system inspection.

Inspector conclusion

Fictional example: only recorded checks are shown; other items are not assessed.

CUSTOMER ACKNOWLEDGEMENT

The customer received the findings and, where relevant, risks of critical defects. Signature acknowledges receipt, not repair authorization or waiver of rights.

CUSTOMER - ACKNOWLEDGED

Example customer

10/26/2026, 9:10:00 AM

Signed by: Example customer · Signed at: 10/26/2026, 9:10:00 AM

PHOTOS



Photo 1 - Vehicle identification - Generated illustrative image; not an inspected vehicle.

Not enough photos for a full inspection (2-4 real photos recommended).