Example workshop

Technician: Example inspector

REPORT

Fitted parts warranty

10/26/2026

EXAMPLE

Peugeot 308 · 2017

Date	Mileage	Customer
10/26/2026	**45,000 mi**	**Example customer**

Part 1

Part	Front brake pads
Brand and part number	Example brand
Supplier	Example supplier
Warranty	24 luni

Fitting and terms

Fitting date	2026-10-26
Odometer at fitting	88234.709 mi
Labour warranty	6 luni
Warranty conditions	Warranty does not cover normal wear.

Records fitted parts and the warranty terms stated by the workshop or supplier.

Inspector conclusion

Fictional example: only recorded checks are shown; other items are not assessed.

CUSTOMER ACKNOWLEDGEMENT

The customer received the findings and, where relevant, risks of critical defects. Signature acknowledges receipt, not repair authorization or waiver of rights.

CUSTOMER - ACKNOWLEDGED

Example customer

10/26/2026, 9:10:00 AM

Signed by: Example customer · Signed at: 10/26/2026, 9:10:00 AM

PHOTOS



Photo 1 - Vehicle identification - Generated illustrative image; not an inspected vehicle.

Not enough photos for a full inspection (2-4 real photos recommended).