Example workshop

Technician: Example inspector

REPORT

Pre-purchase inspection - 150 points

10/26/2026

EXAMPLE

Mazda CX-5 · 2020

Date	Mileage	Customer
10/26/2026	**45,000 mi**	**Example customer**

3 items need attention

We recommend addressing them soon.

4	3	0
OK	Needs attention	Critical

Calculated summary

Inspection coverage	7 / 150 assessed (0 not applicable)
Exterior	7.5 / 10
Engine	5.0 / 10
Chassis	7.5 / 10
Interior	10.0 / 10
Road Test	10.0 / 10
Overall score - assessed checks only	7.9 / 10

Scoring method
OK = 10, attention = 5, critical = 1; mean of assessed checks. Missing checks receive no score.

Exterior

CHECK	VALUE / NOTE	STATUS
Paint scratches and stone chips		Needs attention
Panel alignment and gap consistency		OK
Findings and evidence references	Superficial body marks; fictional example.	

Engine

CHECK	VALUE / NOTE	STATUS
Oil leaks on and around the engine		Needs attention

Findings and evidence references	Identify the source of the oil traces.

Chassis

CHECK	VALUE / NOTE	STATUS
Visible brake pad thickness		Needs attention
Brake discs for visible wear, corrosion and damage		OK
Findings and evidence references	Brake pads need measurement and further assessment.	

Interior

Seat belt webbing, retraction, buckles and locking		OK

Road Test

Brake response during gentle, progressive slowing		OK

Mark each point only from an inspection actually performed. Keep unchecked and non-applicable items explicit. Estimates are indicative in the stated currency; the score and its rules do not certify the vehicle.

Inspector conclusion

Fictional example: only recorded checks are shown; other items are not assessed.

CUSTOMER ACKNOWLEDGEMENT

The customer received the findings and, where relevant, risks of critical defects. Signature acknowledges receipt, not repair authorization or waiver of rights.

CUSTOMER - ACKNOWLEDGED

Example customer

10/26/2026, 9:10:00 AM

Signed by: Example customer · Signed at: 10/26/2026, 9:10:00 AM

PHOTOS



Photo 1 - Vehicle identification - Generated illustrative image; not an inspected vehicle.

Not enough photos for a full inspection (2-4 real photos recommended).