Example workshop

Technician: Example inspector

REPORT

Timing belt / chain - kit replacement

10/26/2026

EXAMPLE

Dacia Logan 1.5 dCi · 2017

Date	Mileage	Customer
10/26/2026	**45,000 mi**	**Example customer**

1 items need attention

We recommend addressing them soon.

3	1	0
OK	Needs attention	Critical

Installed kit

Timing drive	Belt
Replacement date	2026-10-26
Odometer at replacement	73321.801 mi
Kit brand and part number	Example kit
Water pump	Replaced
Coolant used	G12
Accessory belt	Replaced

Fitting checks

CHECK	VALUE / NOTE	STATUS
Removed kit condition		● Needs attention
Timing marks / locking		● OK
Tension to manufacturer spec		● OK
Start and run after fitting		● OK

Next replacement

At odometer	110604.072 mi
Interval source	Manufacturer service schedule
Notes	Old belt with cracked teeth.

Inspector conclusion

Fictional example: only recorded checks are shown; other items are not assessed.

CUSTOMER ACKNOWLEDGEMENT

The customer received the findings and, where relevant, risks of critical defects. Signature acknowledges receipt, not repair authorization or waiver of rights.

CUSTOMER - ACKNOWLEDGED

Example customer

10/26/2026, 9:10:00 AM

Signed by: Example customer · Signed at: 10/26/2026, 9:10:00 AM

PHOTOS



Photo 1 - Vehicle identification - Generated illustrative image; not an inspected vehicle.

Not enough photos for a full inspection (2-4 real photos recommended).