Example workshop

Technician: Example inspector

REPORT

Tyres - change, inspection and storage

10/26/2026

EXAMPLE

Renault Clio · 2019

Date	Mileage	Customer
10/26/2026	**45,000 mi**	**Example customer**

Recorded checks are OK

No issues were recorded.

8	0	0
OK	Needs attention	Critical

Operation and set

Operation	Storage
Documented set	Before work

Tyre / wheel 1

CHECK	VALUE / NOTE	STATUS
Position / axle	Front left	
Set / action	Removed	
Brand and model	Continental WinterContact	
Size	205/55 R16	
Season	Winter	
DOT code	2324	
Tread depth	6.8 mm	
Measured pressure	32	
Pressure unit	psi	
Tyre condition		● OK
Rim condition		● OK

Tyre / wheel 2

CHECK	VALUE / NOTE	STATUS

Position / axle	Front right	
Set / action	Removed	
Brand and model	Continental WinterContact	
Size	205/55 R16	
Season	Winter	
DOT code	2324	
Tread depth	6.7 mm	
Measured pressure	32	
Pressure unit	psi	
Tyre condition		● OK
Rim condition		● OK

Tyre / wheel 3

CHECK	VALUE / NOTE	STATUS
Position / axle	Rear left	
Set / action	Removed	
Brand and model	Continental WinterContact	
Size	205/55 R16	
Season	Winter	
DOT code	2324	
Tread depth	7.1 mm	
Measured pressure	32	
Pressure unit	psi	
Tyre condition		● OK
Rim condition		● OK

Tyre / wheel 4

CHECK	VALUE / NOTE	STATUS
Position / axle	Rear right	
Set / action	Removed	
Brand and model	Continental WinterContact	

Size	205/55 R16	
Season	Winter	
DOT code	2324	
Tread depth	7 mm	
Measured pressure	32	
Pressure unit	psi	
Tyre condition		● OK
Rim condition		● OK

Storage and completion

CHECK	VALUE / NOTE	STATUS
Storage location	A-12 / 04	
Storage reference	HOTEL-2026-0148	
TPMS check		● Not checked

Inspector conclusion

The removed set is documented for storage. Tread depths and pressures are example readings, not universal limits or specifications. TPMS was not checked.

CUSTOMER ACKNOWLEDGEMENT

The customer received the findings and, where relevant, risks of critical defects. Signature acknowledges receipt, not repair authorization or waiver of rights.

CUSTOMER - ACKNOWLEDGED

Example customer

10/26/2026, 9:10:00 AM

Signed by: Example customer · Signed at: 10/26/2026, 9:10:00 AM

PHOTOS



Photo 1 - Vehicle identification - Generated illustrative image; not an inspected vehicle.

Not enough photos for a full inspection (2-4 real photos recommended).