Example workshop

Technician: Example inspector

REPORT

Wheel alignment - before and after

10/26/2026

EXAMPLE

Hyundai Tucson · 2021

Date	Mileage	Customer
10/26/2026	**45,000 mi**	**Example customer**

Specifications and setup

Specification source	Example reference

Vehicle setup and conditions
Tyre pressures and steering position checked before measurement.

Measurement document format (enter decimal degrees)	Decimal degrees

Measured angle 1

Position / axle	Front left
Angle	Individual toe
Before - decimal degrees	0.18 °
After - decimal degrees	0.08 °

Notes
Illustrative values; actual specifications depend on the vehicle.

Checks and work

Work performed	Illustrative measurement and adjustment.

Enter angles as numbers in decimal degrees. Comparisons use only the recorded limits, specification source and reference; they do not certify the overall condition of the vehicle.

Inspector conclusion

Fictional example: only recorded checks are shown; other items are not assessed.

CUSTOMER ACKNOWLEDGEMENT

The customer received the findings and, where relevant, risks of critical defects. Signature acknowledges receipt, not repair authorization or waiver of rights.

CUSTOMER - ACKNOWLEDGED

Example customer

10/26/2026, 9:10:00 AM

Signed by: Example customer · Signed at: 10/26/2026, 9:10:00 AM

PHOTOS



Photo 1 - Vehicle identification - Generated illustrative image; not an inspected vehicle.

Not enough photos for a full inspection (2-4 real photos recommended).